

Owner / Applicant Information

Kurt Workman
Workman Services LLC
8143 OLD STATE ROAD 37N

MARTINSVILLE IN 46151

Phone 3176968633

Email KURT@WORKMANSERVICES.COM

Project Information

Swinger MBA
1309 Alderly Rd.

Indianapolis 46260

County MARION

Project Type New ☐ Addition ☐ Alteration ☒ Existing ☐ Change of Occupancy ☐

Project Status ☒ U F=Filed U or Null=Unfiled

IDHS Issued Correction order? ☐ No Has Violation been Issued? ☒ yes

Violation Issued by: LBD

Local Building Official

Phone: Email:

Local Fire Official

Phone: Email:

Variance Details

Code Name: 2005 Indiana Residential Code (675 IAC 14-4.3)
R308.4

Conditions:

DEMONSTRATION THAT PUBLIC HEALTH, SAFETY, AND WELFARE ARE PROTECTED:

1=Non-compliance with the rule will not be adverse to the public health, safety or w

2

2= Applicant will undertake alternative actions in lieu of compliance with the rule to ensure that granting of the variance will not be adverse to public health, safety, or welfare. Explain why alternative actions would be adequate (be specific).

Facts: Since the window manufacturer no longer makes this window, the application of a protective laminate to the glass is commonly used. See attached specification document.

DEMONSTRATION OF UNDUE HARDSHIP OR HISTORICALLY SIGNIFICANT STRUCTURE:

☐

Imposition of the rule would result in an undue hardship (unusual difficulty) because of physical limitations of the construction site or its utility services.

☐

Imposition of the rule would result in an undue hardship (unusual difficulty) because of major operational problems in the use of the building or structure.

☒

Imposition of the rule would result in an undue hardship (unusual difficulty) because of excessive costs of additional or altered construction elements.

☐

Imposition of the rule would prevent the preservation of an architecturally or a historically significant part of the building or structure

Facts: Since the window manufacturer no longer makes this window, two windows would require full replacement and would not match the remaining window units in the home. Excessive additional cost would also be incurred by the home owner.