Owner / Applicant Information	
Kirk Livingstone	
Vasa Fitness Group of Lafayette	
1259 S. 800 E.	
OREM UT 84097	
Phone 8126550421	
Email KIRK@VASAFITNESS.COM	
Submitter Information	
Mark Stroud	
DeWees Construction	
35 N. Baldwin Street	
Bargersville IN	
Phon∈ 3174221654	
Email mark@deweesconstruction.com	
Designer Information	
Blake Olson	
Galloway	
6162 S. Willow Drive	
Greenwood Village CO	
Phon∈ 3037708884	
Email blakeolson@gallowayus.com	
Project Information	
Vasa Fitness	
5325 East Thompson Road	
Indianapolis IN 46237	
County MARION	
Project Type New Addition Alteration Existing Y Change of Occupancy	
Project Status F F=Filed U or Null=Unfiled	
IDHS Issued Correction order? No Has Violation been Issued? No	
Violation Issued by: NA	
Local Building Official	
Phone: 3174221654 Email: planreview.class1@indy.gov	
Local Fire Official  Phono: 2174221/F4 Fmail: and toulor@indu.gov	
Phone: 3174221654 Email: ed.taylor@indy.gov	

Code Name:	2014 IFC	
	907.5.2.3.1	
Conditions:	2014 InFC sec. 907.5.2.3.1 Public areas and common areas. Visible alarm notification appliances shall be provided in public areas and common areas.	
	The steam room and the sauna will not have visible alarm notification appliances. Marked as 121C and 121D on the print	
DEMONSTRATION THAT PUBLIC HEALTH, SAFETY, AND WELFARE ARE PROTECTED:		
	1=Non-compliance with the rule will not be adverse to the public health, safety or w	
1	2= Applicant will undertake alternative actions in lieu of compliance with the rule to ensure that granting of the variance will not be adverse to public health, safety, or welfare. Explain why alternative actions would be adequate (be specific).	
Facts:	Strobe/alarm are located outside of require rooms in the spa area marked as 121B.	
DEMONSTRATION OF UNDUE HARDSHIP OR HISTORICALLY SIGNIFICANT STRUCTURE:		
	Imposition of the rule would result in an undue hardship (unusual difficulty) because of physical limitations of the construction site or its utility services.	
Υ	Imposition of the rule would result in an undue hardship (unusual difficulty) because of major operational problems in the use of the building or structure.	
Υ	Imposition of the rule would result in an undue hardship (unusual difficulty) because of excessive costs of additional or altered construction elements.	
	Imposition of the rule would prevent the preservation of an architecturally or a historically significant part of the building or structure	

Facts: Due to high heat, humidity, water strobe/alarm will be inoperable if located in required areas.

Variance Details