Owner / Applicant Information	
Jady Hill	
Jady W Hill	
525 CHURCH ST	
FRENCH LICK IN 47432	
Phon∈ 8127971381	
Email JADYHILL@GMAIL.COM	
Submitter Information	
Andrew Smallwood	
Renaissance Design Build, INC	
117 S. Indiana Ave	
Sellersburg IN	
Phon∈ 8122465897	
Email asmallwood.rdbi@sbcglobal.net	
<u>Designer Information</u>	
RONALD STILLER	
RCS and Associates	
4800 Smith Rd	
FLOYDS KNOBS IN	
Phon∈ 8129231019	
Email astiller@digicove.com	
Project Information	
Hill Event Center LLC	
525 S Church St	
FRENCH LICK IN 47432	
County ORANGE	
Project Type New Addition Alteration Y Existing Y Change of Occupancy	
Project Status F F=Filed U or Null=Unfiled	
IDHS Issued Correction order? No Has Violation been Issued? No	
<u>Violation Issued by:</u> NA	
Local Building Official	
Phone: 3174176650 Email: rwineinger@dhs.in.gov	
Local Fire Official	
Phone: 3174176650 Email: rwineinger@dhs.in.gov	

Code Name:	2014 IBC
	IBC 903.2.1.2
Conditions:	Sprinkler system is required in the attic area of the building. This is not possible due to lack of access and obstructions due to framing.
DEMONSTRATION THAT PUBLIC HEALTH, SAFETY, AND WELFARE ARE PROTECTED:	
	1=Non-compliance with the rule will not be adverse to the public health, safety or w
1	2= Applicant will undertake alternative actions in lieu of compliance with the rule to ensure that granting of the variance will not be adverse to public health, safety, or welfare. Explain why alternative actions would be adequate (be specific).
Facts:	There will be no mechanical or electrical components installed in the attic space which would cause fire hazard. Other precautions will be taken in lieu of the code requirements.
DEMONSTRATION OF UNDUE HARDSHIP OR HISTORICALLY SIGNIFICANT STRUCTURE:	
Υ	Imposition of the rule would result in an undue hardship (unusual difficulty) because of physical limitations of the construction site or its utility services.
	Imposition of the rule would result in an undue hardship (unusual difficulty) because of major operational problems in the use of the building or structure.
	Imposition of the rule would result in an undue hardship (unusual difficulty) because of excessive costs of additional or altered construction elements.
	Imposition of the rule would prevent the preservation of an architecturally or a historically significant part of the building or structure
Facts:	There is limited access to the attic area and would therefore make installation of a sprinkler system difficult or even impossible.

Variance Details