Owner / Applicant Information
Jay Patel Holiday Inn Express
2918 CARLSON
HAMMOND IN 46323
Phon∈ 3127726210
Email JAY@SSCON.COM
Submitter Information
Jacquelyn Espinoza
thyssenkrupp Elevator 355 Eisenhower Lane South
333 Elserinower Lane South
Lombard IN
Phon∈ 6306524051
Email jackie.espinoza@thyssenkrupp.com
Desired Information
Project Information Heliday Inn Everage Hammand
Holiday Inn Express Hammond 2918 Carlson
Hammond IL 46323
County LAKE
Project Type New Y Addition Alteration Existing Change of Occupancy
Project Status F = Filed U or Null=Unfiled
IDHS Issued Correction order? Has Violation been Issued?
Violation Issued by: NA
Local Building Official Phone: 2198536316 Email: kochk@gohammond.com
Local Fire Official
Phone: 2198536316 Email: Chiefinspector@gohammond.com

Variance Details ASME A17.1 2007 Code Name: 3.19.4.1,3.19.4-5,3.26.8 This is hydraulic MRL technology which the Indiana code has not yet adopted. Conditions: DEMONSTRATION THAT PUBLIC HEALTH, SAFETY, AND WELFARE ARE PROTECTED: 1=Non-compliance with the rule will not be adverse to the public health, safety or w 1 2= Applicant will undertake alternative actions in lieu of compliance with the rule to ensure that granting of the variance will not be adverse to public health, safety, or welfare. Explain why alternative actions would be adequate (be specific). This type of elevator is safely being used in Indiana and across the country. Facts: DEMONSTRATION OF UNDUE HARDSHIP OR HISTORICALLY SIGNIFICANT STRUCTURE: Imposition of the rule would result in an undue hardship (unusual difficulty) because of physical limitations of the construction site or its utility services. Imposition of the rule would result in an undue hardship (unusual difficulty) because of major operational problems in the use of the building or structure. Imposition of the rule would result in an undue hardship (unusual difficulty) because of excessive costs of additional or altered construction elements.

Imposition of the rule would prevent the preservation of an

Facts:

architecturally or a historically significant part of the building or structure

Lack of machine room allows for more usable space in the building.