Owner /	Applicant	<u>Information</u>

Michael Zauberman Platos Court LLC 270 MADISON AVE 19TH FLOOR NEW YORK NY 10016 Phon€ 6464727995

Email DHRUV@NEWCASTLENYC.COM

Submitter Informatio

Phone:

8123329763

Email:

submitter information		
Melissa Tupper		
RTM Consultants, Inc.		
6640 Parkdale Place		
Suite J		
Indianapolis IN		
Phone 3173297700		
Email tupper@rtmconsultants.com		
Designer Information		
Howard Douglas Bruce		
Tabor Bruce Architecture & Design Inc		
1101 S Walnut Street		
Bloomington IN		
Phone 8123326258		
Email dbruce@taborbruce.com		
Project Information		
Platos Court Renovations		
2036 N Walnut Street		
BLOOMINGTON IN 47408		
County MONROE		
Project Type New Addition Alteration Y Existing Change of Occupancy		
Project Status F F=Filed U or Null=Unfiled		
IDHS Issued Correction order? Has Violation been Issued? yes		
Violation Issued by: LBD		
Local Building Official		
Phone: 8123329763 Email: jgerstbauer@co.monroe.in.us		
Local Fire Official		

clappt@bloomington.in.gov

Variance Details

1

Code Name: Other Code (Not in the list provided)

2014 IBC, 1029

Conditions: The project involves a renovation of existing 2-story apartment buildings. As a part of the renovation the layout of the apartments was rearranged and an additional bedroom was added to the units. The existing windows in the newly created bedrooms do not comply with all of the requirements for emergency escape and rescue openings. See attachment for the window dimensions and where the windows fall short of complying. See drawings for window locations.

DEMONSTRATION THAT PUBLIC HEALTH, SAFETY, AND WELFARE ARE PROTECTED:

1=Non-compliance with the rule will not be adverse to the public health, safety or w

- 2= Applicant will undertake alternative actions in lieu of compliance with the rule to ensure that granting of the variance will not be adverse to public health, safety, or welfare. Explain why alternative actions would be adequate (be specific).
- Facts: There are existing bedrooms with windows that are the same size as the windows in the newly created units.

The windows all fall short in one of the three required dimensions, but exceed minimum requirements in the other required dimensions. All windows comply with the maximum sill height. See attachment.

DEMONSTRATION OF UNDUE HARDSHIP OR HISTORICALLY SIGNIFICANT STRUCTURE:

	Imposition of the rule would result in an undue hardship (unusual difficulty) because of physical limitations of the construction site or its utility services.
	Imposition of the rule would result in an undue hardship (unusual difficulty) because of major operational problems in the use of the building or structure.
Υ	Imposition of the rule would result in an undue hardship (unusual difficulty) because of excessive costs of additional or altered construction elements.
	Imposition of the rule would prevent the preservation of an architecturally or a historically significant part of the building or structure
Facts:	It is a cost hardship to replace the existing windows with complying ones. The 1st floor windows are in a brick wall and the 2nd floor windows are in dormers, so replacing them is difficult and costly. There would also still be existing bedrooms that had the same windows the newly created bedrooms do.