Owner / Applicant Information
Christie Miller
Handcrafted Doors
12171 CR 34
GOSHEN IN 46528
Phone 5742026505
Email PD.FREEDOMBUILDERS@GMAIL.COM
Submitter Information
Carrie Ballinger
RTM Consultants, Inc.
6640 Parkdale Place, Ste J
Indianapolis IN
Phon∈ 3173297700
Email ballinger@rtmconsultants.com
Designer Information
Doug Graham
Barr Design Group
502 S Main St
Goshen IN
Phon∈ 5745346531
Email doug@barrdesigngroup.com
3 3 1
Project Information
Handcrafted Doors
7245 S 1200 W
Millersburg IN 46543
County ELKHART
Project Type New Y Addition Alteration Existing Change of Occupancy
Project Status U F=Filed U or Null=Unfiled
IDHS Issued Correction order? No Has Violation been Issued? No
Violation Issued by: NA
Local Building Official Phone: 5749714678 Email: kwilliams@elkhartcounty.com
Local Fire Official
Phone: 5749714678 Email: ctfd@bnin.net

Saala Niamaa	other Code (Not in the list provided)
Code Name:	· ,
	Section 903.2.4.1
Conditions:	An automatic sprinkler system is required in buildings containing wood working operations that exceed 2,500 square feet. The variance request is to permit a dust collection system in accordance with NFPA 664 2012 Edition, Standard for the Prevention of Fires and Explosions in Wood Processing and Woodworking Facilities, in lieu of an automatic sprinkler system.
	The building will be 1-story, Type VB construction, and will be approximately 8,400 square feet.
DEMO	NSTRATION THAT PUBLIC HEALTH, SAFETY, AND WELFARE ARE PROTECTED:
	1=Non-compliance with the rule will not be adverse to the public health, safety or w
2	2= Applicant will undertake alternative actions in lieu of compliance with the rule to ensure that granting of the variance will not be adverse to public health, safety, or welfare. Explain why alternative actions would be adequate (be specific).
Facts:	1. The code requires an automatic sprinkler system because of the potential amount of combustible dust that could be generated during woodworking operations. The installation o a dust collection system in acordance with NFPA 664 will reduce the potential amount of combustible dust in the air, therefore the lack of a sprinkler system is not adverse to safety.
	2. The building will have at least 60 feet open space surrounding it.
	3. Numerous similar variances have been approved, including 18-09-09, 18-08-09, 18-07-70 18-06-23, 18-03-62, 18-03-13, 17-11-12, 17-10-53, 17-10-10, 17-03-54, 17-01-42, 16-10-37, 16-10-31, 16-10-02.

Facts:	It would be a cost hardship to provide sprinklers as this building is located in a rural area with no water supply.
	Imposition of the rule would prevent the preservation of an architecturally or a historically significant part of the building or structure
Υ	Imposition of the rule would result in an undue hardship (unusual difficulty) because of excessive costs of additional or altered construction elements.
	Imposition of the rule would result in an undue hardship (unusual difficulty) because of major operational problems in the use of the building or structure.
	Imposition of the rule would result in an undue hardship (unusual difficulty) because of physical limitations of the construction site or its utility services.