Owner / Applicant Information		
Erica Delgado		
355 EISENHOWER LANE SOUTH		
LOMBARD IL 60148		
Phon∈ 7085163830		
Email ERICA.DELGADO@THYSSENKRUPP.COM		
Submitter Information		
Erica Delgado		
355 Eisenhower Lane South		
Lombard IN		
Phon∈ 7085163830		
Email erica.delgado@thyssenkrupp.com		
Project Information St Paul Square		
St Paul Square 452 W Chicago St		
Valporaiso IL 46385		
County PORTER		
Project Type New Y Addition Alteration Existing Change of Occupancy		
Project Status U F=Filed U or Null=Unfiled		
Project Status U F=Filed U or Null=Unfiled IDHS Issued Correction order? Has Violation been Issued?		
IDHS Issued Correction order? Has Violation been Issued?		
IDHS Issued Correction order? Has Violation been Issued? Violation Issued by: NA Local Building Official Phone: 2194628325 Email: vthrasher@valpo.us		
IDHS Issued Correction order? Has Violation been Issued? Violation Issued by: NA Local Building Official		

Variance Details		
Code Name:	ASME A17.1 2007	
	33.19.4.1, 3.19.4.4, 3.19.4.5	
Conditions:	ASME A17.1 2007 3.19.4.1, 3.19.4.4, 3.19.4.5	
	THIS IS NEW HYDRAULIC MRL TECHNOLOGY, WHICH HAS NOT BEEN ADOPTED BY THE STATE OF INDIANA. PLEASE REFERENCE APPROVED VARIANCE #14-05-04.	
DEMONSTRATION THAT PUBLIC HEALTH, SAFETY, AND WELFARE ARE PROTECTED:		
	1=Non-compliance with the rule will not be adverse to the public health, safety or w	
1	2= Applicant will undertake alternative actions in lieu of compliance with the rule to ensure that granting of the variance will not be adverse to public health, safety, or welfare. Explain why alternative actions would be adequate (be specific).	
Facts:	SEE ATTACHED. THIS TYPE OF ELEVATOR IS SAFE AND IS BEING USED IN OTHER BUILDINGS IN INDIANA AND ACROSS THE COUNTRY.	
DEMONSTRATION OF UNDUE HARDSHIP OR HISTORICALLY SIGNIFICANT STRUCTURE:		
	Imposition of the rule would result in an undue hardship (unusual difficulty) because of physical limitations of the construction site or its utility services.	
	Imposition of the rule would result in an undue hardship (unusual difficulty) because of major operational problems in the use of the building or structure.	
	Imposition of the rule would result in an undue hardship (unusual difficulty) because of excessive costs of additional or altered construction elements.	
	Imposition of the rule would prevent the preservation of an architecturally or a historically significant part of the building or structure	

Facts: LACK OF MACHINE ROOM ALLOWS FOR ORE USABLE SPACE IN THE BUILDING.