

Owner / Applicant Information

Brian Wood  
PSC Industries  
1100 WEST MARKET STREET

LOUISVILLE KY 40203

Phone 3175475439

Email BRIANW@PSCOFKY.COM

Submitter Information

Timothy Callas  
J & T Consulting, LLC  
8220

INDIANAPOLIS IN

Phone 3178894300

Email tcallas@jtconsult.us

Project Information

PSC Industries  
6790 East 32nd Street

Indianapolis IN 46226

County MARION

Project Type New  Addition  Alteration  Existing  Change of Occupancy

Project Status  U F=Filed U or Null=Unfiled

IDHS Issued Correction order?  No Has Violation been Issued?  No

Violation Issued by: NA

Local Building Official

Phone:  Email:

Local Fire Official

Phone:  Email:

Variance Details

Code Name: Other Code (Not in the list provided)

2014 IFC 507.5.2

Conditions: An existing S-1 Occupancy, Type IIB construction building has an existing out of service hydrant (see photos) that has been determined by Indianapolis Fire Department (IFD) inspections to be in the collapse zone. IFD has requested that the hydrant and adjacent PIV remain out of service and be bagged out of service.

DEMONSTRATION THAT PUBLIC HEALTH, SAFETY, AND WELFARE ARE PROTECTED:

1

1=Non-compliance with the rule will not be adverse to the public health, safety or w

2= Applicant will undertake alternative actions in lieu of compliance with the rule to ensure that granting of the variance will not be adverse to public health, safety, or welfare. Explain why alternative actions would be adequate (be specific).

Facts: 1.The existing building is protected with automatic fire suppression throughout.  
2.There are 3 active hydrants two to the west of building and one to the east of building (see areal drawings and photos) that are within 600 feet.

DEMONSTRATION OF UNDUE HARDSHIP OR HISTORICALLY SIGNIFICANT STRUCTURE:

Imposition of the rule would result in an undue hardship (unusual difficulty) because of physical limitations of the construction site or its utility services.

Imposition of the rule would result in an undue hardship (unusual difficulty) because of major operational problems in the use of the building or structure.

Y

Imposition of the rule would result in an undue hardship (unusual difficulty) because of excessive costs of additional or altered construction elements.

Imposition of the rule would prevent the preservation of an architecturally or a historically significant part of the building or structure.

Facts: The owner's undue hardship involves the cost of repairing the existing hydrant while IFD will not use it based upon being in the collapse zone. In addition there are 3 other hydrants that comply with Section 507.5.1 Exception # 2 IFC (WITHIN 600 FEET).