Owner / Applicant Information
Philip h Cohn
GMA Properties LLC-S 5520
3740 N. LAFAYETTE ROAD
A-3 INDIANAPOLIS IN 46222
Phon∈ 3179871076
Email PHIL@ARNOLDMEYER.COM
Project Information
Head Start
5520 West 38th Street
Indianapolis 46222
County MARION
Project Type New Addition Alteration Y Existing Change of Occupancy
Project Status U F=Filed U or Null=Unfiled
IDHS Issued Correction order? No Has Violation been Issued? yes
Violation Issued by: LFD
Local Building Official
Phone: 3173275529 Email: planreview.class1@indy.gov
Local Fire Official
Phone: 3173275529 Email: margie.bovard@indy.gov

Variance Details

Code Name: 1998 Indiana Fire Code (675 IAC 22-2.2) Section 912

Conditions: Sprinkler system needs to be disconnected.

DEMONSTRATION THAT PUBLIC HEALTH, SAFETY, AND WELFARE ARE PROTECTED:

1=Non-compliance with the rule will not be adverse to the public health, safety or w

	I non compliance marking the new second conception of the passion of the second of the	
1	2= Applicant will undertake alternative actions in lieu of compliance with the rule to ensure that granting of the variance will not be adverse to public health, safety, or welfare. Explain why alternative actions would be adequate (be specific).	
Facts:	Sprinkler system was disconnected. Proper steps were taken in order for system to be properly disconnected. Attached are blueprints demonstrating same.	
DEMONSTRATION OF UNDUE HARDSHIP OR HISTORICALLY SIGNIFICANT STRUCTURE:		
	Imposition of the rule would result in an undue hardship (unusual difficulty) because of physical limitations of the construction site or its utility services.	
	Imposition of the rule would result in an undue hardship (unusual difficulty) because of major operational problems in the use of the building or structure.	
	Imposition of the rule would result in an undue hardship (unusual difficulty) because of excessive costs of additional or altered construction elements.	
	Imposition of the rule would prevent the preservation of an architecturally or a historically significant part of the building or structure	
Facts:		