Owner / Applicant Information		
Roger Winter		
John Elpers Contracting		
6747 ST. JOSEPH ROAD		
EVANSVILLE IN 47720		
Phon€ 8124028000		
Email ELPERSA@JOHNELPERS.COM		
Submitter Information		
Annette Elpers		
John Elpers Contracting		
21 Mount Ashley Road		
EVANSVILLE IN		
Phone 8124028000		
Email elpersa@johnelpers.com		
Droject Information		
Project Information		
Roger & Kathy Winter		
6747 St. Joseph Road		
EVANSVILLE IN 47720		
County VANDERBURGH		
Project Type New Y Addition Alteration Existing Change of Occupancy		
Project Status F F=Filed U or Null=Unfiled		
IDHS Issued Correction order?NoHas Violation been Issued?No		
Violation Issued by: LBD		
Local Building Official		
Phone: 8124367872 Email: dballew@evansville.in.gov		
Local Fire Official		
Phone: 8124367872 Email: dballew@evansville.in.gov		

Variance Details

Code Name:	Other Code (Not in the list provided)	
	2020 Indiana Residential Code	
Conditions:	Spindles going down to the basement are 4 1/4 inch and code is 4 inches.	
DEMONSTRATION THAT PUBLIC HEALTH, SAFETY, AND WELFARE ARE PROTECTED:		
	1=Non-compliance with the rule will not be adverse to the public health, safety or w	
1	2= Applicant will undertake alternative actions in lieu of compliance with the rule to ensure that granting of the variance will not be adverse to public health, safety, or welfare. Explain why alternative actions would be adequate (be specific).	
Facts:		
DEMONS	TRATION OF UNDUE HARDSHIP OR HISTORICALLY SIGNIFICANT STRUCTURE:	
Υ	Imposition of the rule would result in an undue hardship (unusual difficulty) because of physical limitations of the construction site or its utility services.	
	Imposition of the rule would result in an undue hardship (unusual difficulty) because of major operational problems in the use of the building or structure.	
	Imposition of the rule would result in an undue hardship (unusual difficulty) because of excessive costs of additional or altered construction elements.	
	Imposition of the rule would prevent the preservation of an architecturally or a historically significant part of the building or structure	
Facts:		